

# Rotorua Museum Te Whare Taonga Seismic Strengthening and Restoration

I & E Committee Update – November 2024





20/11 – photo courtesy of  
Greeves Scaffolding





20/11 – photo courtesy of  
Greeves Scaffolding







FRCM wall application 30/10



Zone 3 basement ceiling propping 26/11



Zone 3 foundation excavation 02/12



FRCM wall application 26/11



PSG walkaround – Atrium 26/11




Rachel Bath 30/10



Zone 1 columns fire stopped 02/12



South Wing (zone 1) wall lining 30/10



Lift shaft steel install 11/11  
Document Set ID: 21066456  
Version: 1, Version Date: 04/12/2024



North roof building wrap 02/12



Exterior paint prep 02/12



Roof tile removal 11/11



Flashing install 26/11

Document Set ID: 2106556  
Version: 1, Version Date: 04/12/2024



---

 **+64 7 348 4199**

Document Set ID: 21066456  
Version: 1, Version Date: 04/12/2024

 **rotorualakescouncil.nz**

 **DX Box JX10503, Rotorua 3046**

**ROTORUA**  
LAKES COUNCIL